

# Oil Field Environmental Incident Summary

**Incident:** 20160803151120      **Date/Time of Notice:** 08/03/2016 15:11

**Responsible Party:** Creek Energy Services

**Well Operator:** LIME ROCK RESOURCES III-A, L.P.

**Well Name:** STATE JAEGER 1-21-16H-142-94

**Field Name:** MURPHY CREEK

**Well File #:** 20411

**Date Incident:** 8/2/2016      **Time Incident:** 16:30

**Facility ID Number:**

**County:** DUNN

**Twp:** 142

**Rng:** 94

**Sec:** 21

**Qtr:**

**Location Description:**

**Submitted By:** Robyn Espinoza

**Received By:**

**Contact Person:** Robyn Espinoza  
4413 Sims St.  
Dickinson, ND 58601

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Truck Overflow

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	2	Barrels	1	Barrels		
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 12/7/2016

**Clean Up Concluded:** 8/13/2016

**Risk Evaluation:**

Contaminated surface material

**Areal Extent:**

**Potential Environmental Impacts:**

Contaminated surface material

**Action Taken or Planned:**

A vac truck was dispatched to recover all standing fluids, the remaining contaminated materials will be removed and properly disposed of.

**Wastes Disposal Location:**

**Agencies Involved:**

**Updates**

---

**Date:** 8/4/2016    **Status:** Reviewed - Assigned to Other Agency

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, the release was contained to the well pad. NDIC retains oversight.