

Oil Field Environmental Incident Summary

Incident: 20160805112454 **Date/Time of Notice:** 08/05/2016 11:24

Responsible Party: LIME ROCK RESOURCES III-A, L.P.

Well Operator: LIME ROCK RESOURCES III-A, L.P.

Well Name: DVORAK 10-1H

Field Name: MURPHY CREEK

Well File #: 17234

Date Incident: 8/4/2016 **Time Incident:** 13:30

Facility ID Number:

County: DUNN

Twp: 142

Rng: 95

Sec: 10

Qtr:

Location Description:

Submitted By: Dustin Tescher

Received By:

Contact Person: Dustin Tescher
1111 BAGBY, SUITE 4600
HOUSTON, TX 77002

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	1.5	Barrels	1.5	barrels

Brine

Other	3	Barrels
--------------	---	---------

Description of Other Released Contaminant:

Standing rain water was also recovered with the oil

Inspected:

Written Report Received: 8/24/2016

Clean Up Concluded: 8/5/2016

Risk Evaluation:

none expected

Areal Extent:

Potential Environmental Impacts:

none expected

Action Taken or Planned:

Stuffing box packing was replaced to eliminate any future releases.

Wastes Disposal Location: TBD

Agencies Involved:

Updates

Date: 8/8/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a stuffing box leak, was contained to the constructed well site according to the report. NDIC retains oversight.