

Oil Field Environmental Incident Summary

Incident: 20160821231722 **Date/Time of Notice:** 08/21/2016 23:17

Responsible Party: ENERPLUS RESOURCES USA CORPORATION

Well Operator: ENERPLUS RESOURCES USA CORPORATION

Well Name: ATLAS 149-93-33C-28H

Field Name: MANDAREE

Well File #: 23227

Date Incident: 8/21/2016 **Time Incident:** 10:00

Facility ID Number:

County: DUNN

Twp: 149

Rng: 93

Sec: 33

Qtr:

Location Description: Release was confined to the well pad

Submitted By: Tony Lucero

Received By:

Contact Person: Chuck Antle
US BANK TOWER
950 17TH ST STE 2200
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels	10	Barrels	10	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/29/2016

Clean Up Concluded: 8/23/2016

Risk Evaluation:

No applicable health hazards.

Areal Extent:

All released material was confined to the well pad.

Potential Environmental Impacts:

The entire release was confined to the well pad.

Action Taken or Planned:

The well was shut in and the affected gauge was replaced. Free-standing liquids were recovered and returned to the system. Contaminated debris was excavated and disposed of offsite an an approved site. Follow applicable inspection and maintenance procedures to avoid a recurrence of this incident.

Wastes Disposal Location: Free-standing liquids were recovered and returned to the system. Contaminated debris was excavated and disposed of offsite an an approved site.

Agencies Involved: BLM, BIA, Three Affiliated Tribes

Updates

Date: 8/25/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Schiermeister, Robin

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on the pad. The release occurred on tribal land. Tribe/BIA retains oversight.