

Oil Field Environmental Incident Summary

Incident: 20160926144842 **Date/Time of Notice:** 09/26/2016 14:48

Responsible Party: Petro Harvester Operating Company, LLC

Well Operator: PETRO HARVESTER OPERATING COMPANY, LLC

Well Name: North Bly CTB

Field Name: RIVAL

Well File #:

Date Incident: 9/26/2016 **Time Incident:** 13:30 **Facility ID Number:** 210629-01

County: BURKE **Twp:** 163 **Rng:** 91 **Sec:** 30 **Qtr:** SW SW

Location Description: Bly 30 CTB

Submitted By: Gary Watson

Received By:

Contact Person: Mark Bonnie
5851 LEGACY CIRCLE
SUITE 500
PLANO, TX 75024

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1.1 Mile

Distance Nearest Water Well: 1.1 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	Barrels	0.5	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No explosive or health hazard risk.

Areal Extent:

Flowline ruptured ~ 5' north of the Bly 30 CTB containment - 3' x 5' area.

Potential Environmental Impacts:

The approximate 0.5 barrel release affected only a 3' x 5' area of cultivated soils.

Action Taken or Planned:

NDIC Field Inspector Jim Potts was notified of the leak telephonically. The affected soil in the 3' x 5' area will be excavated and hauled to an approved disposal facility. The flowline will be repaired and pressure tested and the removed affected soil replaced with black dirt. The surface owner will be identified and contacted regarding the incident.

Wastes Disposal Location: An approved disposal facility.

Agencies Involved:

Updates

Date: 9/26/2016 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Follow-up is necessary.

Date: 9/27/2016 **Status:** Inspection

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 12:25. 66 degrees F, sunny, south wind 0-5 mph. Observed the site and took photos. It appeared the release occurred in a cultivated field north of the northeast corner of the well pad. Oil-stained soils were noted near and around a stick that had been stuck in the soil with a piece of blue cloth attached to it. Visible extent of the release was hard to determine due to plant growth and wet soils. Further follow-up needed.