

# Oil Field Environmental Incident Summary

**Incident:** 20161014072529      **Date/Time of Notice:** 10/14/2016 07:25  
**Responsible Party:** Petro Harvester Operating Company, LLC  
**Well Operator:** PETRO HARVESTER OPERATING COMPANY, LLC  
**Well Name:** BUSCH TRUST 31-30 164-92 B  
**Field Name:** PORTAL      **Well File #:** 31720  
**Date Incident:** 10/13/2016      **Time Incident:** 1015      **Facility ID Number:**  
**County:** BURKE      **Twp:** 164      **Rng:** 92      **Sec:** 31      **Qtr:** SE SW

## Location Description:

**Submitted By:** Gary Watson      **Received By:**

**Contact Person:** Mark Bonnie  
5851 LEGACY CIRCLE  
SUITE 500  
PLANO, TX 75024

**General Land Use:** Cultivated

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 17700 Feet

**Distance Nearest Water Well:** 6100 Feet

**Type of Incident:** Other

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	1.5	Barrels	1.5	Barrels		
<b>Brine</b>	1.5	Barrels	1.5	Barrels		

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

No explosive or health hazard risk.

**Areal Extent:**

100'x50' cultivated area north of the pad location was sprayed with a fine mist of released fluids.

**Potential Environmental Impacts:**

No impact to surface water or ground water. Majority of released fluids contained on the facility site. Fine mist (100'x50') of released fluids sprayed off lease to the north of the pad location.

**Action Taken or Planned:**

NDIC Field Inspector Jim Potts was notified of the incident telephonically. The affected facility site soil will be scraped up, collected and hauled to an approved disposal facility. The cultivated lands affected by the 100'x50' released fluid misting will be scraped up, collected and hauled to an approved disposal facility. The removed soil will be replaced with black dirt to the satisfaction of the surface owner. The flare system fluid knock-out will be inspected to insure functionality.

**Wastes Disposal Location:** An approved disposal facility.

**Agencies Involved:**

**Updates**

---

**Date:** 10/14/2016 **Status:** Reviewed - Follow-up Required

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, the release was not contained. Further follow-up required.

---

**Date:** 11/2/2016 **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 5:10, 11/2/2016.

Spray to the north of the flare roughly 150 yards. The dike and its side walls appear to have been scraped and the impacted materials removed; however, the field appears to have been left unremediated. Contact responsible party to clarify cleanup intentions on the impacted field.

More follow-up is necessary to ensure proper cleanup.