

Oil Field Environmental Incident Summary

Incident: 20161103160736 **Date/Time of Notice:** 11/03/2016 16:07

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name:

Field Name: TIOGA

Well File #:

Date Incident: 11/3/2016 **Time Incident:** 09:30

Facility ID Number:

County: WILLIAMS

Twp: 158 **Rng:** 95 **Sec:** 36 **Qtr:** SE NW

Location Description: TMU-I-129. NoR GG was hydrovacating out an area to repair a 6 inch fuel gas line and encountered contaminated soil on the pipeline ROW. 158N-95W- Sec 36 NW/SE

Submitted By: Alberto Yates

Received By:

Contact Person: Troy Brunsell
1501 MCKINNEY
HOUSTON, TX 77010

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.5 Mile

Distance Nearest Water Well: 0.5 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other					60	gallons

Description of Other Released Contaminant:

Hydrocarbon contaminated soil was found while hydro - vacing a 6 " fuel gas line .

Inspected:

Written Report Received: 1/13/2017

Clean Up Concluded: 1/5/2017

Risk Evaluation:

At this time, there are no known immediate risks associated with the contaminated soil discovered.

Areal Extent:

Approximately a 10' X 10' area on the pipeline ROW

Potential Environmental Impacts:

All impacts remained in the pipeline ROW. No sensitive areas were impacted.

Action Taken or Planned:

Upon discovery of the release, a vacuum truck was dispatched to recover the free liquids. Arrangements were made for the impacted material to be cleaned up and disposed of to an approved waste facility

Wastes Disposal Location: The recovered waste will be taken to an approved waste disposal facility.

Agencies Involved:

Updates

Date: 11/3/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, topsoil along a pipeline right-of-way was impacted by hydrocarbons. Further follow-up needed.

Date: 11/10/2016 **Status:** Inspection

Author: Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site 11/09/16 at 9:30 a.m. Impact appears to NE of TMU-I-129 battery building. No free liquids seen; soil is excavated around pipe 48.467296,-102.892661. No odors noticed. Follow-up necessary.