

General Environmental Incident Summary

Incident: 1477 **Date/Time Notice:** 7/4/2011 1820 **DEM Incident No:**

Responsible Party: Renaissance Transport

Date Incident: 7/4/2011 **Time Incident:** 1814 **Duration:**

County: Pembina **Twp:** 162 **Rng:** 54 **Sec:** 25 **Qtr:**

Lat: 48.82633 **Long:** -97.56735 **Method:** Derived from TRS

Location Description: approx 1 mile north of the intersection of Hwy 5 and 18, 5 miles ne of Cavalier; AH - 10/25/2012 - Could be T162R054S36 and/or T162R053S30 and/or T162R053S31.

Submitted By: Andy Cashman

Affiliation: ND Highway Patrol

Address:

City:

State:

Zip:

Received By: Cameron David

Contact Person: Craig
NW29-9-19W
Brandon, MB

Distance Nearest Occupied Building: 1 Miles

Type of Incident: Vehicle Accident

Description of Released Contaminant: road oil (tack) CQ1SH emulsion and some diesel fuel

Volume Spilled: 5000.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** No

Cause of Incident:

truck rolled over in the ditch, diesel from truck and road oil from one of the trailers leaked out into the ditch.

Risk Evaluation:

Low

of Fatalities: 0 **# of Injuries:** 1 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

none waste will be recovered and site cleaned up.

Action Taken or Planned:

6 truckloads of sand were placed at either end of the spill, Mayo Constr. is recovering the liquids and any soils.
Tim Mayo, 701-265-8438

Wastes Disposal Location: liquids and soil will be used in Mayo's asphalt operation.

Agencies Involved: NDDDES, State Highway Patrol

