

General Environmental Incident Summary

Incident: 1567 **Date/Time Notice:** 11/9/2011 1545 **DEM Incident No:**
Responsible Party: American Crystal Sugar Company
Date Incident: 11/9/2011 **Time Incident:** 0500 **Duration:** 1 hours
County: Pembina **Twp:** 159 **Rng:** 51 **Sec:** 14 **Qtr:**
Lat: 48.59303 **Long:** -97.17905 **Method:** Derived from TRS
Location Description: 8152 County Highway 44 North, Drayton, ND
Drayton, ND 58225-0190

Submitted By: Steve Lindquist **Affiliation:**

Address:

City: **State:** **Zip:**

Received By:

Contact Person: Steve Lindquist
8152 County Highway 44 North
PO Box 190
Drayton, ND 58225-0190

Distance Nearest Occupied Building: 2 Miles

Type of Incident: Tank Leak

Description of Released Contaminant: Beet Molasses

Volume Spilled: 3500.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

Air was introduced into the molasses during pumping to the tank. This caused foaming. The tank is monitoring by weight, not volume

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

None.

Action Taken or Planned:

The molasses will either be absorbed with dried beet pulp or it will be pumped out.

Wastes Disposal Location: The molasses or molasses/bulp mixture will be applied to the land west of the Mud Pond. It will be worked into the soil.

Agencies Involved:

