

General Environmental Incident Summary

Incident: 2033 **Date/Time Notice:** 9/4/2013 0748 **DEM Incident No:**
Responsible Party: Southern Energy Transportation
Date Incident: 9/3/2013 **Time Incident:** 1800 **Duration:** 1 minutes
County: Mountrail **Twp:** 156 **Rng:** 91 **Sec:** 27 **Qtr:**
Lat: 48.30543 **Long:** -102.36410 **Method:** Derived from TRS
Location Description: 6150 Hwy 8, Stanley, ND 58784,
Bridger Transfer Services' Stanley 3A Station

Submitted By: David Lamay **Affiliation:**
Address:
City: **State:** **Zip:**

Received By:

Contact Person: Otis Randle
15510 Wright Brothers Dr.
Addison, TX 75001

Distance Nearest Occupied Building: 1 Miles

Type of Incident: hose leaking

Description of Released Contaminant: Crude Oil

Volume Spilled: 0.25 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

Heat pressurized the loading line and the hose gasket had a minor cut in it and caused the release of a negligible amount of crude oil onto driveway

Risk Evaluation:

No risks associated with release

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 09 - other

Potential Environmental Impacts:

No likelihood of environmental impacts, everything was clean up immediately following knowledge of the leak

Action Taken or Planned:

all stained rocks were picked up and disposed of into a spill container for disposal

Wastes Disposal Location: The container will likely go to Indian Hills Disposal Center

Agencies Involved:

Updates

Date: 9/4/2013 **Status:** Reviewed - No Action Required

Author: Roberts, Kris

Updated Volume:

Notes:

Very small release of crude oil lost and immediately cleaned up, according to the report. No follow-up is necessary on this one.