

General Environmental Incident Summary

Incident: 2085 **Date/Time Notice:** 10/26/2013 1410 **DEM Incident No:**

Responsible Party: CHS Inc

Date Incident: 10/26/2013 **Time Incident:** 1400 **Duration:** 1 hours

County: Pembina **Twp:** 162 **Rng:** 51 **Sec:** 28 **Qtr:** SE NE SE

Lat: 48.82551 **Long:** -97.23866 **Method:** Derived from TRS

Location Description: Next to the grain bins north of the CHS elevator at 9721 1st St. in Joliette, ND 58271-4600

Submitted By: Peter Mutschler

Affiliation:

Address:

City:

State:

Zip:

Received By:

Contact Person: Peter Mutschler
5500 Cenex Drive
MS 305
St. Paul, MN 55077

Distance Nearest Occupied Building: 0.75 Miles

Type of Incident: Vehicle Accident

Description of Released Contaminant: Diesel Fuel

Volume Spilled: 20.00 gallons

Ag Related: Yes

EPA Extremely Hazardous Substance: No

Reported to NRC: No

Cause of Incident:

Semi Tractor Trailer owned by Farmer was delevering grain to CHS Grain Elevator. As they used the hoist on the truck to empty the grain it tipped over on to its side. The trucks fuel tank was on the ground side and the fuel leaked out the fill cap untill the truck was up righted.

Risk Evaluation:

Minor

of Fatalities: 0

of Injuries: 1

Affected Medium: 03 - soil

Potential Environmental Impacts:

Contaminated soil will need to be recovered

Action Taken or Planned:

The area around the fuel tank was cleaned. Free product was recovered with buckets. The rest of the product was tied up with floor dry and soil. All impacted soil will be excavated.

Wastes Disposal Location: We will find out for sure on Monday, but we typically try to landfill the recovered material

Agencies Involved: NDDDES, Local Law Enforcement

Updates

Date: 10/28/2013 **Status:** Inspection

Author: Stockdill, Scott

Updated Volume:

Notes:

Email from Pembina County Emergency Manger to Scott Stockdill on inspection.

"Please see attached photos on site at Joliette CHS elevator. I have also attached a marked map of the location of the spill. The contaminated material was moved by what appeared to be either a small trachoe or possibly a skid steer and placed on heavy duty polyurethane. The gravel under the contaminated material is extremely hard and compacted, much like a gravel road and the fuel was not able to penetrate very deep under the surface of the road. Most of the contaminate was soil from the ditch. Cenex Harvest State corporate has been made aware of the spill and are handling the situation based on internal regulations. The elevator manager is holding the material until a proper disposal plan is in place."

CHS manager Company man was contacted and it was recommended that all the diesel stained soil be removed and placed on impermeable tarp.

No more Follow Up needed.

Date: 10/28/2013 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Volume:

Notes:

Incident impacted area where truck rolled over. Pembina County Emergency Manager Andrew Kirking will be inspecting 10/28/2013.