

General Environmental Incident Summary

Incident: 2117 **Date/Time Notice:** 11/21/2013 1200 **DEM Incident No:**
Responsible Party: Brett Brown
Date Incident: 11/21/2013 **Time Incident:** 0800 **Duration:** 15 minutes
County: Williams **Twp:** 155 **Rng:** 103 **Sec:** 20 **Qtr:**
Lat: 48.23125 **Long:** -103.94450 **Method:** Interpolation from map
Location Description: 5639 151st Ave NW; Williston, ND - Pioneer Generating Station Ph II

Submitted By: Sherry White **Affiliation:** Kiewit
Address: 1149 260th St
City: Sergeant Bluff **State:** IA **Zip:**

Received By:

Contact Person:

5639 151st Ave NW
Williston, ND

Distance Nearest Occupied Building:

Type of Incident: Hydraulic oil pump cracked

Description of Released Contaminant: hydraulic oil

Volume Spilled:

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: No

Cause of Incident:

Hydraulic oil pump cracked - causing oil to leak to the ground

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

None

Action Taken or Planned:

Sorbent pads were used as well as soil was shoveled into drums for disposal through Safety Kleen. Sorbent pads will also be placed into drums for disposal through Safety Kleen. When the lift is able to be moved - a back hoe will be brought in to scratch up the top layer - ground is frozen.

Wastes Disposal Location: Safety Kleen will be scheduled for a waste pickup.

Agencies Involved:

Updates

Date: 11/21/2013 **Status:** Reviewed - No Action Required

Author: Roberts, Kris

Updated Volume:

Notes:

Small volume of hydraulic oil lost in pump failure. Fluid was picked up with absorbent pads and impacted soil was removed to extent possible, pending equipment move. At that point additional impacted soil will be removed and be disposed by Safe-T-Clean.