

General Environmental Incident Summary

Incident: 2145 **Date/Time Notice:** 12/9/2013 1830 **DEM Incident No:**

Responsible Party: Mongoose Trucking and Hotshot, LLC

Date Incident: 12/9/2013 **Time Incident:** 1728 **Duration:**

County: Mountrail **Twp:** 152 **Rng:** 91 **Sec:** 17 **Qtr:** SE

Lat: 47.97776 **Long:** -102.34370 **Method:** Navigation quality GPS

Location Description: 17SE 16SW 20NE 21NW

Submitted By: SHELLY STROSNIDER

Affiliation: Safety Coordinator

Address: PO Box 81482

City: Billings

State: MT

Zip: 59108

Received By:

Contact Person: Shawn Yaeger
3532 Hwy 58
PO Box 366
Fairview, MT 59221

Distance Nearest Occupied Building: 1000 Feet

Type of Incident: Vehicle Accident

Description of Released Contaminant: crude oil

Volume Spilled:

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

while making a (N) bound turn onto Hwy 8, Mongoose Trucking and Hotshot, LLC failed to stop at required stop sign at Hwy 23 and Hwy 8 Junction.

Risk Evaluation:

of Fatalities:

of Injuries: 1

Affected Medium:

Potential Environmental Impacts:

containment of spill

Action Taken or Planned:

At the scene of the accident State Police, Mountrail County Sheriff and Incident Command, Big Lease Safety Officer, Strata was onsite tending to the spill.

Wastes Disposal Location:

Agencies Involved: NDDDES, State Highway Patrol, Local Fire Department, Local Law Enforcement, Local Emergency Manager

Updates

Date: 12/9/2013 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

Scott Stockdill, inspector for NDDoH on location this date to assess cleanup efforts and consult with contact.

Date: 12/11/2013 **Status:** Inspection

Author: Stockdill, Scott

Updated Volume:

Notes:

Arrived on location at 9:30 12/11/2013.

Incident involved 180-230 bbls of crude oil released on intersections of Hwys 8 and 23 in Mountrail County after a pickup struck a crude oil tanker, shearing off the fire valves. Spilled oil on the south side of the highway cleaned up, with several more bbls on the north side to be cleaned up.

Contractor originally hired by Mountrail County to contain spill and reopen highway. Tribal officials asked that misted oil on southeast side of highway be scraped up .

More followup necessary to ensure cleanup is completed. This site will be monitored throughout the winter with another thorough inspection done in the spring of 2014.

Date: 12/12/2013 **Status:** Inspection

Author: Stockdill, Scott

Updated Volume:

Notes:

Arrived on location at 14:15 12/12/13.

Cleanup progressing nicely. Instructed contractor to stake down sorbent booms to prevent oil runoff. It was also suggested that the contractor remove the dike constructed around the culvert on the north side of the road.

More followup necessary. This location will be monitored throughout the winter with another thorough inspection done in the spring of 2014.

Date: 5/11/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Volume:

Notes:

Arrived on location 5/11/2015.

No sign of spill at the time of inspection.

No followup is necessary.