

# General Environmental Incident Summary

**Incident:** 2184      **Date/Time Notice:** 1/30/2014      0902      **DEM Incident No:**  
**Responsible Party:** Superpumper Inc  
**Date Incident:** 1/29/2014      **Time Incident:** 2000      **Duration:** 5 minutes  
**County:** Ward      **Twp:** 155      **Rng:** 82      **Sec:** 20      **Qtr:** NW NW NW  
**Lat:** 48.23771      **Long:** -101.25070      **Method:** Interpolation from map  
**Location Description:** Superpumper #33, Farstad Oil  
100 27th Street NE  
Minot ND 58701  
**Submitted By:** Kris Wolla      **Affiliation:** Manager  
**Address:** 100 27th Street NE  
**City:** Minot      **State:** ND      **Zip:** 58702

## Received By:

**Contact Person:** Kris Wolla  
100 27th Street NE  
Minot, ND 58702

**Distance Nearest Occupied Building:** 300 Feet

**Type of Incident:** Unattended Fueling by Customer

**Description of Released Contaminant:** Diesel

**Volume Spilled:** 30.00 gallons

**Ag Related:** No

**EPA Extremely Hazardous Substance:** No

**Reported to NRC:** Unknown

## Cause of Incident:

Truck Driver left the pump unattended while fueling Diesel at the cardtrol station. The trucks tank overflowed onto the concrete surface and followed the man made path towards the containment area. No product reached the containment pond that has a closed gate valve.

## Risk Evaluation:

Frozen ice in trough kept the product from reaching the asphalt paving

**# of Fatalities:** 0

**# of Injuries:** 0

**Affected Medium:** 09 - other

## Potential Environmental Impacts:

None

## Action Taken or Planned:

Spill was absorded with floor dry and sweep up. Contaminated product was scooped up with the front end loader and is still in the bucket of the loader. Loader is housed in warehouse.

**Wastes Disposal Location:** Appropriate Landfill

## Agencies Involved:

## ***Updates***

---

**Date:** 1/30/2014    **Status:** Reviewed - No Action Required

**Author:** Roberts, Kris

### ***Updated Volume:***

### ***Notes:***

Release, due to fueler inattention, remained on facility property on cleanable surface; was contained and cleaned up immediately. No followup is necessary. Phone call confirmed details.