

# General Environmental Incident Summary

**Incident:** 3238      **Date/Time Notice:** 3/10/2014      1700      **DEM Incident No:**  
**Responsible Party:** ONEOK Rockies Midstream  
**Date Incident:** 3/7/2014      **Time Incident:** 1900      **Duration:** 1 hours  
**County:** McKenzie      **Twp:** 145      **Rng:** 101      **Sec:** 33      **Qtr:**  
**Lat:** 47.33835      **Long:** -103.55700      **Method:** Interpolation from map  
**Location Description:** 530 Rough Rider Road  
Grassy Butte, ND 58634

**Submitted By:** Jason Lyons      **Affiliation:**  
**Address:** 2700 Lincoln Ave.  
**City:** Sidney      **State:** MT      **Zip:** 59270

## Received By:

**Contact Person:** Jason Lyons  
2700 Lincoln Ave  
Sidney, MT 59270

**Distance Nearest Occupied Building:** 1 Miles      **Release Contained:** Yes

**Type of Incident:** compressor oil line leak

**Description of Released Contaminant:** compressor oil

**Volume Spilled:** 20.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** No

## Cause of Incident:

Oil filter piping rubbed a hole in oil line.

## Risk Evaluation:

There were no immediate risks to human health or the environment.

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 01 - air

## Potential Environmental Impacts:

There were no impacts to surface water or groundwater.

## Action Taken or Planned:

Oil was removed with absorbant materials.

**Wastes Disposal Location:** Recovered waste will be disposed at licensed landfill.

**Agencies Involved:** NDDDES

## **Updates**

---

**Date:** 3/10/2014    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Volume:**

**Notes:**

According to the incident summary, this spill impacted the surrounding areas. Followup is necessary.

---

**Date:** 3/25/2014    **Status:** Inspection

**Author:** Espe, Brady

**Updated Volume:**

**Notes:**

I arrived at the site. The temperature was 31 °F, with wind from the northwest at 5 mph. I looked around the site; there was no evidence that anything left the site. Oil spill was cleaned up, and the compressor station was operating. No further followup needed at this time.