

General Environmental Incident Summary

Incident: 3266 **Date/Time Notice:** 3/26/2014 1155 **DEM Incident No:**
Responsible Party: Minnesota Power
Date Incident: 3/26/2014 **Time Incident:** 1100 **Duration:** 5 minutes
County: Morton **Twp:** 140 **Rng:** 86 **Sec:** 4 **Qtr:**
Lat: 46.97971 **Long:** -101.55390 **Method:** Interpolation from map
Location Description: 5198 30th Street, New Salem, ND

Submitted By: William Fraundorf **Affiliation:**
Address: 30 W. Superior St
City: Duluth **State:** MN **Zip:** 55802

Received By:

Contact Person: Timothy Mork
5198 30th Street
New Salem, ND 58563

Distance Nearest Occupied Building: 50 Feet **Release Contained:** Yes

Type of Incident: Spill Event

Description of Released Contaminant: Gasoline

Volume Spilled: 2.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

Gasoline transfer to equipment resulted in an overfill with < 2 gallons being spilled to soil.

Risk Evaluation:

Minimal risk; spill was cleaned up immediately. Spill was reported immediately.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Minimal impacts to the environment.

Action Taken or Planned:

Floor-dry was spread to absorb and pick-up the gasoline. Equipment filling procedures will be reviewed to prevent a recurrence.

Wastes Disposal Location: Will be incinerated as hazardous waste (assumed D001) at a Clean Harbors facility.

Agencies Involved:

Updates

Date: 3/26/2014 ***Status:*** Reviewed - No Action Required

Author: Roberts, Kris

Updated Volume:

Notes:

Small spill immediately cleaned up to extent possible. Residual volatile liquid will evaporate quickly. No inspection necessary.