

# General Environmental Incident Summary

**Incident:** 3275      **Date/Time Notice:** 4/2/2014      1530      **DEM Incident No:**  
**Responsible Party:** ONEOK Rockies Midstream  
**Date Incident:** 4/2/2014      **Time Incident:** 1400      **Duration:** 2 hours  
**County:** McKenzie      **Twp:** 151      **Rng:** 102      **Sec:** 1      **Qtr:** NE NE  
**Lat:** 47.93515      **Long:** -103.67030      **Method:** Navigation quality GPS  
**Location Description:** Alexander Compressor Station  
36th St NW  
Alexander, ND 58831  
**Submitted By:** Kim Rudningen      **Affiliation:** ONEOK Rockies Midstream  
**Address:** 2700 Lincoln Ave SE  
**City:** Sidney      **State:** MT      **Zip:** 59270

## Received By:

**Contact Person:** Kim Rudningen  
2700 Lincoln Ave SE  
Sidney, MT 59270

**Distance Nearest Occupied Building:** 0.5 Miles      **Release Contained:** Yes

**Type of Incident:** Tank Overflow

**Description of Released Contaminant:** Ethylene glycol

**Volume Spilled:** 150.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** No

## Cause of Incident:

The high temperature shutdown valve on the tank malfunctioned causing the glycol to boil over and spill onto the ground surrounding the glycol tank.

## Risk Evaluation:

There are no immediated risks to health or environment as a result of this release.

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

No ground water was impacted due to this release. Soil surrounding the tank was effected but will be excavated and disposed of. The spill was contained on the facility site.

## Action Taken or Planned:

The overflow was immediatly stopped and the spill was contained to the soil surrounding the tank. The soil will be excavated and removed to a landfill.

**Wastes Disposal Location:** Permitted landfill.

## Agencies Involved:

## **Updates**

---

**Date:** 4/2/2014    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

### **Updated Volume:**

### **Notes:**

According to the incident summary, this spill impacted areas not associated with an E & P location. Followup is necessary.

---

**Date:** 4/1/2015    **Status:** Inspection

**Author:** Espe, Brady

### **Updated Volume:**

### **Notes:**

I arrived at the site at 13:47 p.m. The weather is cloudy, 53°F, with the wind from the northwest at 10-20 mph. I was able to talk to personnel about the spill. It was indicated that the spill was contained within the building where the tank is located. No further followup needed at this time. 47.934483; -103.670772