

General Environmental Incident Summary

Incident: 3284 **Date/Time Notice:** 4/11/2014 1315 **DEM Incident No:**

Responsible Party: Pilot Travel Centers

Date Incident: 4/11/2014 **Time Incident:** 0845 **Duration:** 1 minutes

County: McKenzie **Twp:** 150 **Rng:** 102 **Sec:** 35 **Qtr:**

Lat: 47.76160 **Long:** -103.69940 **Method:** Interpolation from map

Location Description: Location is Schluberger Williston 7 crew site. Directions are south on hwy 85 to hwy 68 by wild bison truck stop continue south on 68 to 24th street mile marker 25 turn right go west for 2 miles turn right for 0.1 mile turn left for 0.6 miles in to location. Site is also referred to as SLB Williston 7, Emerald.

Submitted By: Max Burmeister

Affiliation:

Address: 9874 Main Street

City: Woodstock

State: ND

Zip: 30188

Received By:

Contact Person: Joey Cupp
5508 Lonas Road
Knoxville, TN 37909

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Tank Overflow

Description of Released Contaminant: Red Dye Diesel Fuel

Volume Spilled: 50.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Employees overflowed the tank wagon during filling operations.

Risk Evaluation:

One individual involved in the incident was sprayed in the face with diesel fuel. No serious affects reported.

of Fatalities: 0

of Injuries: 1

Affected Medium: 03 - soil

Potential Environmental Impacts:

Impacted soil is being removed. No other resources have been impacted or have the potential to be impacted.

Action Taken or Planned:

Fuel spilled on to soil in the well pad staging area. Crew has been dispatched to excavate and remove from the site all soil impacted with diesel. A confirmation sample for TPH DRO has also been requested.

Wastes Disposal Location: Undetermined.

Agencies Involved:

Updates

Date: 4/12/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Volume:

Notes:

Release of diesel fuel occurred and was contained on a drilling location. NDIC retains oversight. Report forwarded to NDIC.

Date: 4/14/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

NDIC has reviewed and determined that the incident location is not on a well location. Therefore, followup is necessary.

Date: 4/15/2014 **Status:** Inspection

Author: Martin, Russell

Updated Volume:

Notes:

4/15/2014 at 12:49, on location. Location is on Emerald's Pirate 5 and 6 well pad. Met with on-site Emerald personnel who indicated location of spill. Area indicated shows no staining. Some piles of dirt along north side of wellpad. Call to report contact to confirm piles of dirt do not contain any impacted material.