

General Environmental Incident Summary

Incident: 3481 **Date/Time Notice:** 9/30/2014 **DEM Incident No:**
Responsible Party: Pinkys Aggregate
Date Incident: 9/29/2014 **Time Incident:** 1500 **Duration:** 5 minutes
County: Rolette **Twp:** 163 **Rng:** 69 **Sec:** 2 **Qtr:**
Lat: 48.96440 **Long:** -99.54783 **Method:** Interpolation from map
Location Description: Intersection of 107st and 53rd Ave

Submitted By: Shabeeb Abdul Khader **Affiliation:**
Address: 10707 52nd Ave
City: Rolla **State:** ND **Zip:** 58367

Received By:

Contact Person: Shabeeb Abdul Khader
10707 52nd Ave
Rolla , ND 58367

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: engine leak

Description of Released Contaminant: Anti Freeze

Volume Spilled: 0.30 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

Leak from the radiator due to tear on the radiator cap thread

Risk Evaluation:

None

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

None

Action Taken or Planned:

The spill was contained using diapers and then collected and taken offsite

Wastes Disposal Location: Subcontractors disposal bin

Agencies Involved:

Updates

Date: 9/30/2014 **Status:** Reviewed - No Action Required

Author: Roberts, Kris

Updated Volume:

Notes:

This is another report of the same basic incident. Very small volume released, and cleaned up. No onsite inspection is required.