

# General Environmental Incident Summary

**Incident:** 3527      **Date/Time Notice:** 8/2/2014      **DEM Incident No:**  
**Responsible Party:** RES Americas  
**Date Incident:** 8/2/2014      **Time Incident:**      **Duration:** 1 days  
**County:** Rolette      **Twp:** 163      **Rng:** 69      **Sec:** 3      **Qtr:**  
**Lat:** 48.96685      **Long:** -99.57172      **Method:** Interpolation from map  
**Location Description:** Laydown yard of the Border Winds wind energy project

**Submitted By:** Shabeeb Abdul Khader      **Affiliation:** Environmental Supervisor  
**Address:** 10707 52nd Ave  
**City:** Rolla      **State:** ND      **Zip:** 58367

## Received By:

**Contact Person:** Shabeeb Abdul Khader  
10707 52nd Ave  
Rolla , ND 58367

**Distance Nearest Occupied Building:** 2 Miles      **Release Contained:** Yes

**Type of Incident:** Hydraulic line leak

**Description of Released Contaminant:** No. hydraulic fluid.

**Volume Spilled:** 2.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Unknown

## Cause of Incident:

A hydraulic fluid connection on the loader broke when it was probably hit by a rock while operating.

## Risk Evaluation:

None

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

None

## Action Taken or Planned:

Vehicle removed from operation and repaired. The spoil contained using diapers, tarps and drain pads. The collected hydraulic fluid and soil was collected in a container after the equipment was fixed.

**Wastes Disposal Location:** Collected in the special waste bin in the laydown yard.

## Agencies Involved:

## **Updates**

---

**Date:** 8/2/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Volume:**

**Notes:**

This report of hydraulic oil was received by email on Nov 2, 2014, not Aug 2, 2014. Both incident and reporting date have been entered manually. Please determine reason, and inspect the facility.

---

**Date:** 11/6/2014    **Status:** Inspection

**Author:** O'Gorman, Brian

**Updated Volume:**

**Notes:**

Arrived on location at 12:50. 34 degrees, cloudy, NW wind 10-15 mph. Spoke with company representative who showed me photos of the release and led me to the incident location. Observed and took photos. No impacts were noted. Further followup not required.