

General Environmental Incident Summary

Incident: 3549 **Date/Time Notice:** 11/14/2014 **DEM Incident No:**
Responsible Party: RES Earth & Cable
Date Incident: 11/13/2014 **Time Incident:** 1500 **Duration:** 10 minutes
County: Rolette **Twp:** 163 **Rng:** 70 **Sec:** 10 **Qtr:**
Lat: 48.95346 **Long:** -99.70126 **Method:** Interpolation from map
Location Description: Border Winds Project. Location Turbine 12 access entrance.

Submitted By: Shabeeb Abdul Khader **Affiliation:** Environmental Supervisor
Address: 10707 52nd Ave
City: Rolla **State:** ND **Zip:** 58367

Received By:

Contact Person: Shabeeb Abdul Khader
10707 52nd Ave
Rolla , ND 58367

Distance Nearest Occupied Building: 1 Miles **Release Contained:** Yes

Type of Incident: Tank Leak

Description of Released Contaminant: Diesel

Volume Spilled: 0.50 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Drain valve on the fuel tank turned on when possibly hit with a lock.

Risk Evaluation:

None

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

None. on ground.

Action Taken or Planned:

The spill was contained and the spoil collected in container. It was then disposed into the special waste bin in the laydown yard.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 11/14/2014 **Status:** Reviewed - No Action Required

Author: Stockdill, Scott

Updated Volume:

Notes:

According to the incident summary, this spill was immediately contained, and cleanup was properly handled. No followup is necessary.