

General Environmental Incident Summary

Incident: 3605 **Date/Time Notice:** 1/13/2015 10:57 **DEM Incident No:**
Responsible Party: Marathon Oil (Involved Contractor - Stallion)
Date Incident: 1/10/2015 **Time Incident:** 19:00 **Duration:** 12 hours
County: Mountrail **Twp:** 150 **Rng:** 93 **Sec:** 3 **Qtr:**
Lat: 47.84652 **Long:** -102.56930 **Method:** Navigation quality GPS

Location Description: Stevenson 24-34TFH API NO. 33-061-03368 From the Marathon office travel ~ 81 miles N on Hwy 22 to intersection of Hwys 22/23. * Turn right (east), travel ~ 8 miles (past Four Bears Casino/Lodge and bridge over Lake Sakakawea to BIA 6(Sanish)/92nd Ave NW. * Turn right (south), travel 9 miles to 30th St NW. * Turn right (west), travel 0.5 miles to location on the left (south).

Submitted By: Troy Dockter **Affiliation:** Marathon Oil

Address: 3172 Hwy 22 N

City: Dickinson **State:** ND **Zip:** 58601

Received By:

Contact Person: Troy Dockter
3172 Hwy 22 N
Dickinson, ND 58601

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: Sewage Accident

Description of Released Contaminant: Blackwater from rig camp lift stations

Volume Spilled: **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** No

Cause of Incident:

Five lift stations behind rig camps were found to be frozen. Upon further investigation it was discovered that there was blackwater spill around the lift stations. Involved contractor was called to assess the situation and figure out a plan moving forward. Lift stations were replaced and they have started to clean and haul away frozen blackwater. No fluid left location and proper notifications have been made. Spill volume between 10 and 25 gallons.

Risk Evaluation:

None

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Cleanup will occur minimizing any potential negative impact to contacted soil.

Action Taken or Planned:

Due to cold temperatures, fluid froze to ground quickly upon release eliminating potential soil absorption. Involved contractor was called to location to complete cleanup. Material was chipped away and removed from location.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 1/13/2015 ***Status:*** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

Black water leak on a drilling location. Follow-up is necessary to determine appropriate handling and cleanup.

Date: 1/13/2015 ***Status:*** Correspondence

Author: Harries, Alison

Updated Volume:

Notes:

The responsible party representative called at 15:10, 1/13/2015, with the correct lat/long and a better location description. The record was updated accordingly.

Date: 2/2/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Volume:

Notes:

According to the incident report, the spill occurred within the MHA boundaries.

Forward to BIA/Tribal authorities.