

General Environmental Incident Summary

Incident: 3610 **Date/Time Notice:** 1/16/2015 10:00 **DEM Incident No:**

Responsible Party: Hiland Partners

Date Incident: 1/16/2015 **Time Incident:** 10:00 **Duration:**

County: Williams **Twp:** 155 **Rng:** 102 **Sec:** 28 **Qtr:** NE SE

Lat: 48.22050 **Long:** -103.79920 **Method:** Calculated

Location Description: Bethel Compressor Station, Williams County, ND

Submitted By: Austin Schneider

Affiliation:

Address: 302 N Independence

City: Enid,

State: OK

Zip:

Received By:

Contact Person:

302 N Independence
Enid, ND

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Gasket Failure on 2" Hot Oil Line

Description of Released Contaminant: Therminol 55 - Heat Transfer Fluid

Volume Spilled: 1.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

2" gasket on the hot oil line failed resulting less the 1 barrel to be released. 100% containment on location.

Risk Evaluation:

None.

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Zero, Impact limited to facility soil.

Action Taken or Planned:

Contaminated soil will be remediated and stage awaiting analytical prior to disposal.

Wastes Disposal Location: Contaminated soil will be disposed of at Indian Hills Landfill once analytical is received.

Agencies Involved:

Updates

Date: 1/16/2015 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

Release of heat transfer fluid at a compressor station. Followup is necessary.

Date: 2/4/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Volume:

Notes:

Arrived on location 2/4/2015 15:00.

Visible sign of spill at location due to recent snowfall. Employee on location stated spill will be cleaned up in the spring due to frozen conditions of soil.

More followup is necessary.