

General Environmental Incident Summary

Incident: 3694 **Date/Time Notice:** 3/25/2015 **DEM Incident No:**
Responsible Party: Northwest Colorado Transport
Date Incident: 3/24/2015 **Time Incident:** 0945 **Duration:**
County: Dunn **Twp:** 145 **Rng:** 95 **Sec:** 23 **Qtr:**
Lat: 47.35828 **Long:** -102.73950 **Method:** Interpolation from map
Location Description: North side of the road on HWY 200, approximately 2 miles east of the Killdeer roundabout.

Submitted By: Cameron Keeney **Affiliation:**
Address: 122 Central Ave.
City: killdeer **State:** ND **Zip:**

Received By:

Contact Person:

122 Central Ave.
killdeer, ND

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: CMV lost its fuel tank while traveling west bound.

Description of Released Contaminant: Diesel fuel

Volume Spilled: 75.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

The driver's side fuel tank of a CMV became loose and fell off while traveling west bound on HWY 200. Diesel fuel was released out of the fitting in the bottom of the tank that was knocked off after making contact with the road.

Risk Evaluation:

Substance that was released poses a fire hazard as it is a flammable liquid.

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Potential to contaminate soil and rain water in

Action Taken or Planned:

The spill was immediately contained. A crew was dispatched to remediate the spill and remove all contaminated soil and replace the soil with new material.

Wastes Disposal Location:

Agencies Involved:

