

General Environmental Incident Summary

Incident: 3756 **Date/Time Notice:** 5/19/2015 1520 **DEM Incident No:**
Responsible Party: Sanjel USA
Date Incident: 5/18/2015 **Time Incident:** 1630 **Duration:** 15 minutes
County: Williams **Twp:** 154 **Rng:** 100 **Sec:** 19 **Qtr:**
Lat: 48.14949 **Long:** -103.59010 **Method:** Interpolation from map
Location Description: Sanjel USA
511 22nd Ave NE
Williston, Nd 58801
Submitted By: Alan Heltemes **Affiliation:**
Address: 511 22nd Ave NE
City: Williston **State:** ND **Zip:**

Received By:

Contact Person: Alan Heltemes
511 22nd Ave NE
Williston, ND, ND

Distance Nearest Occupied Building: 500 Feet **Release Contained:** Yes

Type of Incident: Damaged 330 gallon chemical tote

Description of Released Contaminant: SI-14-W (Methanol)

Volume Spilled: 330.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

A fork lift operator punctured the bottom of a full tote of SI-14-W (Scale Inhibitor) while unloading the back of a dry van. The operator then removed the tote from the rear of the dry van and set it inside of a bulk plant warehouse equipped with secondary containment. Approximately 40 gallons of the product was spilled onto the ground and inside of the dry van during this process

Risk Evaluation:

The product is listed on the SDS as being Toxic, Flammable and Corrosive. All employees were required to wear full chem gear as well as respiratory protection while cleaning up the spilled product. Decon was completed inside the warehouse by Mirro Image

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

None

Action Taken or Planned:

The spill was contained as per SDS guidelines and Mirro Image Environmental was contacted to facilitate clean-up and remediation of the area. Samples were obtained for analytical testing prior to disposal at a TSD

Wastes Disposal Location: TBD based upon analytical testing results

Agencies Involved:

Updates

Date: 5/19/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Volume:

Notes:

According to the incident summary, this spill impacted areas outside of secondary containment. Followup is necessary.

Date: 9/23/2015 **Status:** Inspection

Author: Martin, Russell

Updated Volume:

Notes:

9/23/2015 at 16:30, on location. Met with site personnel and looked at site where spill occurred. Based on personnel and pictures taken at time of incident, spill location at loading dock, punctured tote was taken to inside of warehouse to contain spill. Spill was then cleaned up by removing impacted facility soil and applying floor dry. No visible staining remains at loading dock. Impacted material currently being stored in drums, a tote, and some buckets, awaiting pickup by disposal company. Responsible party will contact Department when material has been removed.

Date: 2/24/2016 **Status:** Correspondence

Author: Martin, Russell

Updated Volume:

Notes:

Received email from report contact with waste manifest. No further follow-up required.