

General Environmental Incident Summary

Incident: 3804 **Date/Time Notice:** 7/2/2015 1315 **DEM Incident No:**
Responsible Party: Missouri Valley Petroleum
Date Incident: 7/2/2015 **Time Incident:** 1309 **Duration:** 10 minutes
County: Morton **Twp:** 139 **Rng:** 81 **Sec:** 27 **Qtr:**
Lat: 46.82810 **Long:** -100.90070 **Method:** Interpolation from map
Location Description: Tesoro MVP 808 Boundry Road Mandan, ND 58554

Submitted By: Paul Kramer **Affiliation:**
Address: 1722 Mandan Ave
City: Mandan **State:** ND **Zip:** 58554

Received By:

Contact Person: Dave Froelich
1722 Mandan Ave
Mandan, ND 58554

Distance Nearest Occupied Building: 250 Feet **Release Contained:** Yes

Type of Incident: Tank Leak

Description of Released Contaminant: Gasoline

Volume Spilled: 10.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** No

Cause of Incident:

Broken pipe on underground storage tank.

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 01 - air

Potential Environmental Impacts:

None

Action Taken or Planned:

Secondary containment system functioned properly approx. 10 gallons overflowed out from under gas pumps causing fuel to spill on parking lot. No fuel reached any public roads or water ways. The clean-up action was adequate. No further action is needed.

Wastes Disposal Location: Floor dry was used to clean up spilled fuel and disposed of.

Agencies Involved: NDDDES, Local Fire Department

Updates

Date: 7/2/2015 **Status:** Reviewed - Assigned to NDDoH Division **Author:** Stockdill, Scott

Updated Volume:

Notes:

According to the incident summary this spill involved an underground storage tank. Forwarded to NDDH-Waste Management UST program.

Date: 7/24/2015 **Status:** Reviewed - No Action Required **Author:** Vetter, Leon

Updated Volume:

Notes:

The clean-up action was adequate. No further action is needed.