

General Environmental Incident Summary

Incident: 3819 **Date/Time Notice:** 7/10/2015 2100 **DEM Incident No:**
Responsible Party: BRAUN TRUCKING, INC
Date Incident: 7/10/2015 **Time Incident:** 1430 **Duration:** 15 minutes
County: Mountrail **Twp:** 155 **Rng:** 93 **Sec:** 34 **Qtr:**
Lat: 48.21055 **Long:** -102.61560 **Method:** Interpolation from map
Location Description: CORNER OF HIGHWAY 1804 AND 55TH ST NW

Submitted By: JESSE STUNDAL **Affiliation:** SAFETY MANAGER
Address: PO BOX 1033
City: TIOGA **State:** ND **Zip:** 58852

Received By:

Contact Person: JESSE STUNDAL
PO BOX 1033
TIOGA, ND 58852

Distance Nearest Occupied Building: 3200 Feet **Release Contained:** No

Type of Incident: Vehicle Accident

Description of Released Contaminant: SALTWATER

Volume Spilled: 130.00 barrels **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

DRIVER TOOK A TURN TOO FAST GOING FROM HWY 1804 ONTO 55TH ST NW.
TRUCK/TRAILER ROLLED ONTO ITS SIDE ON THE ROADWAY (55TH ST)

Risk Evaluation:

NONE

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

RAIN WATER COULD CAUSE SPILL TO HAVE FURTHER IMPACTS

Action Taken or Planned:

MOUNTRAIL COUNTER DISASTER RELIEF WAS AT THE SCENE AND USED DRY SORB AND ABSORBENT MATS TO CONTAIN SW ON THE ROADWAY. BRAUN TRUCKING VAC TRUCK SUCKED UP 40 BBLS OF STANDING WATER OUT OF THE DITCH AND OFF THE ROAD.

Wastes Disposal Location: 40 BBLS OF WATER VACUUMED OFF THE ROAD AND DITCH WAS DISPOSED OF AT THE WHITE OWL DISPOSAL LOCATED NEAR ROSS, ND

STRATA CORP WAS HIRED TO DO SOIL REMEDIATION AND

CLEAN UP IN THE DITCHES. UNKNOWN PLACE OF DISPOSAL AT THIS TIME

Agencies Involved: Local Law Enforcement, MOUNTRAIL COUNTY DISASTER RELIEF

Updates

Date: 7/10/2015 **Status:** Reviewed - Follow-up Required **Author:** Martin, Russell

Updated Volume:

Notes:

Release is due to vehicle accident on roadway, according to the report. Follow-up is necessary.

Date: 7/13/2015 **Status:** Inspection **Author:** Martin, Russell

Updated Volume:

Notes:

7/13/2015 at 15:25, on location. At intersection of 55th and 1804, both sides of 55th has had excavation work performed in the ditches. Excavated dirt is currently in piles covered with plastic. Most of remaining vegetation around excavation is green and does not appear stressed, however some vegetation next to excavated dirt is yellowed. Called report contact, cleanup company is still working on-site and will be continuing work tomorrow. Responsible party will be sending cleanup report to Department once it has been sent by cleanup company.

Date: 8/25/2015 **Status:** Inspection **Author:** Martin, Russell

Updated Volume:

Notes:

8/25/2015 at 13:11, on location. Excavation has been filled in and leveled off. Erosion control installed on roadway embankments. Electrical conductivity readings all below 3 milliSiemens within the excavation area. No visibly stressed vegetation outside of the excavation area.

Date: 5/12/2016 **Status:** Inspection **Author:** Martin, Russell

Updated Volume:

Notes:

5/12/2016 at 14:30, on location. Inspected site. Vegetation is starting to reestablish in excavated area. None of the vegetation appears stressed. No further follow-up required at this time.