

General Environmental Incident Summary

Incident: 3938 **Date/Time Notice:** 10/15/2015 1447 **DEM Incident No:**
Responsible Party: Thunder Butte Petroleum Services, Inc.
Date Incident: 10/8/2015 **Time Incident:** 1130 **Duration:** 2 minutes
County: Ward **Twp:** 152 **Rng:** 87 **Sec:** 20 **Qtr:**
Lat: 47.97775 **Long:** -101.83550 **Method:** Interpolation from map
Location Description: State Highway 23 and 366th Street SW

Submitted By: Kathryn Cloutier **Affiliation:** Arcadis
Address: 630 Plaza Dr
Suite 100
City: Highlands Ranch **State:** CO **Zip:** 80129

Received By:

Contact Person: Richard Mayer
P.O. Box 1227
New Town, ND 58763

Distance Nearest Occupied Building: 2 Miles **Release Contained:** Yes

Type of Incident: Small equipment leak

Description of Released Contaminant: Diesel

Volume Spilled: 1.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

Cracked fuel line on Belly Dump Truck

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

None

Action Taken or Planned:

Excavator was used to shovel the release into containment and then petroleum-contaminated soil was removed from site.

Wastes Disposal Location: Licensed disposal facility

Agencies Involved:

Updates

Date: 10/16/2015 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, 1 gallon of diesel fuel was released onto soil. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA and EPA.