

General Environmental Incident Summary

Incident: 3949 **Date/Time Notice:** 10/26/2015 1651 **DEM Incident No:**
Responsible Party: Oneok Rockies Midstream, LLC.
Date Incident: 10/22/2015 **Time Incident:** 1100 **Duration:** 1 minutes
County: McKenzie **Twp:** 150 **Rng:** 101 **Sec:** 36 **Qtr:** SE NE
Lat: 47.77188 **Long:** -103.54360 **Method:** Navigation quality GPS
Location Description: Arnegard, ND

Submitted By: Benjamin Rozell **Affiliation:** Site Energy EHS Advisor
Address: 315 Main Street #751
City: New Town **State:** ND **Zip:** 58763

Received By:

Contact Person: Nadia Kyrlova
2700 Lincoln Avenue SE
Sidney, MT 59270

Distance Nearest Occupied Building: 1.15 Miles **Release Contained:** Yes

Type of Incident: Equipment failure

Description of Released Contaminant: Hydraulic Oil

Volume Spilled: 0.20 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

Crew was using a 336 track hoe to clean up ROW when a hydraulic hose on the backside of track hoe boom burst spraying hydraulic fluid. The amount of hydraulic fluid that hit the ground was less than a quart.

Risk Evaluation:

Minor risk

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Minor soil impact

Action Taken or Planned:

The crew contained the spill by putting plastic sheeting and absorbent towels from spill kit underneath the track hoe bucket where most of the fluid was located. The crew then went over and dug the spots of where the hydraulic fluid sprayed.

Wastes Disposal Location: Tervita Alexander, North Dakota

Agencies Involved:

Updates

Date: 10/27/2015 ***Status:*** No Further Action Requested

Author: Souder, Taylor

Updated Volume:

Notes:

No further action required.