

# General Environmental Incident Summary

**Incident:** 3960      **Date/Time Notice:** 11/9/2015      1030      **DEM Incident No:**

**Responsible Party:** Boots Smith Oilfield Services

**Date Incident:** 11/8/2015      **Time Incident:** 1200      **Duration:**

**County:** McKenzie      **Twp:** 153      **Rng:** 95      **Sec:** 4      **Qtr:**

**Lat:** 48.09642      **Long:** -102.89630      **Method:** Interpolation from map

**Location Description:** Pipeline Right-of-Way (ROW)

**Submitted By:** Alex Beach

**Affiliation:**

**Address:** 3015 16th Street SW, Suite

**City:** Minot

**State:** ND

**Zip:** 58701

## Received By:

**Contact Person:** Dwight Brasseaux  
2501 Airport Drive  
Laurel, MS 39441

**Distance Nearest Occupied Building:**

1 Miles

**Release Contained:** No

**Type of Incident:** Water release

**Description of Released Contaminant:** water - The boring water was supplied from South of Hwy 23 Water Depot

**Volume Spilled:** 1.00 barrels

**Ag Related:** No

**EPA Extremely Hazardous Substance:** No

**Reported to NRC:** Unknown

## Cause of Incident:

The boring water followed a previous fracture to the surface resulting in an estimated spill of 1 bbl.

## Risk Evaluation:

There were no injuries or evacuations that occurred as a result of this incident.

**# of Fatalities:** 0

**# of Injuries:** 0

**Affected Medium:** 03 - soil

## Potential Environmental Impacts:

There are no expected environmental impacts at this time.

## Action Taken or Planned:

Boots Smith will insure the boring water is cleaned up as required by the regulating agency. NDDOH

**Wastes Disposal Location:** If the water needs to be disposed of, it will be taken to an approved waste disposal facility.

## Agencies Involved:

## **Updates**

---

**Date:** 11/17/2015 **Status:** Reviewed - Follow-up Required

**Author:** Crowdus, Kory

**Updated Volume:**

**Notes:**

Release on pipeline right of way. Followup is required.

---

**Date:** 12/3/2015 **Status:** Inspection

**Author:** Espe, Brady

**Updated Volume:**

**Notes:**

I traveled to the different sites with the consultant working on the project. Incidents 3948, 3933, 3947, 3960, and 3943 all occurred in the same area. We arrived at the site 3:05 p.m. The weather was sunny, 41°F, with wind from the southwest 10-15 mph. These incidents occurred west of the Silurian Unit 6-1 battery in the draw. The site is accessed from the north along the new pipeline right of way. Access to the draw is not very easy. The fractures occurred high on the banks and flowed into the same area. The site has not been cleaned up; the mud and water are frozen. The plan is to meet with subcontractor on cleaning up the mud and water. Photos will be sent to verify cleanup. More followup needed. 48.09692, -102.89664

---

**Date:** 12/8/2015 **Status:** Correspondence

**Author:** Espe, Brady

**Updated Volume:**

**Notes:**

Plan on how they will be removing the mud from the ravine.