

# General Environmental Incident Summary

**Incident:** 3965      **Date/Time Notice:** 11/14/2015      1225      **DEM Incident No:**

**Responsible Party:** Boots Smith Oilfield Services

**Date Incident:** 11/12/2015      **Time Incident:** 1545      **Duration:**

**County:** McKenzie      **Twp:** 153      **Rng:** 95      **Sec:** 9      **Qtr:**

**Lat:** 48.09574      **Long:** -102.89600      **Method:** Interpolation from map

**Location Description:** Pipeline Right-of-Way (ROW)

**Submitted By:** Alex Beach

**Affiliation:**

**Address:** 3015 16th Street SW, Suite

**City:** Minot

**State:** ND

**Zip:** 58701

**Received By:**

**Contact Person:** Dwight Brasseaux  
2501 Airport Drive  
Laurel, MS 39441

**Distance Nearest Occupied Building:** 1 Miles

**Release Contained:** No

**Type of Incident:** Water release

**Description of Released Contaminant:** water - The boring water was supplied from South of Hwy 23 Water Depot

**Volume Spilled:** 1.00 barrels

**Ag Related:** No

**EPA Extremely Hazardous Substance:** No

**Reported to NRC:** Unknown

**Cause of Incident:**

The boring water followed a fracture in the ground and followed that fracture to the surface resulting in an estimated spill of 1 bbl

**Risk Evaluation:**

There were no injuries or evacuations that occurred as a result of this incident.

**# of Fatalities:** 0

**# of Injuries:** 0

**Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

There are no expected environmental impacts at this time.

**Action Taken or Planned:**

Boots Smith will work with the NDDOH to insure proper clean up of the release.

**Wastes Disposal Location:**

**Agencies Involved:**

## **Updates**

---

**Date:** 11/16/2015 **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

### **Updated Volume:**

#### **Notes:**

According to the report, 1 barrel of water was released onto the surface during boring work along the pipeline right-of-way. Further followup needed.

---

**Date:** 12/3/2015 **Status:** Inspection

**Author:** Espe, Brady

### **Updated Volume:**

#### **Notes:**

Incidents 3932, 3965, and 3966 all occurred in the same area. These incidents occurred south of the Silurian Unit 6-1 battery in the draw. The Hess contact indicated that the site has not been cleaned up. The plan is to meet with subcontractor on cleaning up the mud and water. Photos will be sent verifying cleanup. More followup needed.

---

**Date:** 12/8/2015 **Status:** Correspondence

**Author:** Espe, Brady

### **Updated Volume:**

#### **Notes:**

Received plan on how mud will be removed from the ravine.