

General Environmental Incident Summary

Incident: 3966 **Date/Time Notice:** 11/15/2015 1100 **DEM Incident No:**

Responsible Party: Boots Smith Oilfield Services

Date Incident: 11/13/2015 **Time Incident:** 1120 **Duration:**

County: McKenzie **Twp:** 153 **Rng:** 95 **Sec:** 9 **Qtr:**

Lat: 48.09574 **Long:** -102.89610 **Method:** Interpolation from map

Location Description: Pipeline Right-of-Way (ROW)

Submitted By: Alex Beach

Affiliation:

Address: 3015 16th Street SW, Suite

City: Minot

State: ND

Zip: 58701

Received By:

Contact Person: Dwight Brasseaux
2501 Airport Drive
Laurel, MS 39441

Distance Nearest Occupied Building:

1 Miles

Release Contained: No

Type of Incident: Water release

Description of Released Contaminant: water - The boring water was supplied from South of Hwy 23 Water Depot

Volume Spilled: 0.30 barrels

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

The boring water followed a fracture in the ground and followed that fracture to the surface resulting in an estimated spill of 0.3 bbl

Risk Evaluation:

There were no injuries or evacuations that occurred as a result of this incident.

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

There are no expected environmental impacts at this time.

Action Taken or Planned:

Boots Smith will work with the NDDOH to insure proper clean up of the release.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 11/16/2015 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, 0.3 barrels of boring water were released onto soils through a fracture in the ground during the drilling. Further followup needed.

Date: 12/3/2015 **Status:** Correspondence

Author: Espe, Brady

Updated Volume:

Notes:

Incidents 3932, 3965, and 3966 all occurred in the same area. These incidents occurred south of the Silurian Unit 6-1 battery in the draw. The Hess contact indicated that the site has not been cleaned up. The plan is to meet with subcontractor on cleaning up the mud and water. The companies will send photos verifying cleanup. More followup needed.

Date: 12/8/2015 **Status:** Correspondence

Author: Espe, Brady

Updated Volume:

Notes:

Plan on how they will be removing the mud from the ravine.