

General Environmental Incident Summary

Incident: 3999 **Date/Time Notice:** 1/18/2016 0930 **DEM Incident No:**

Responsible Party: Ferus

Date Incident: 1/18/2016 **Time Incident:** 0930 **Duration:**

County: McKenzie **Twp:** 152 **Rng:** 98 **Sec:** 5 **Qtr:**

Lat: 47.99210 **Long:** -103.21420 **Method:** Derived from TRS

Location Description: Banks Field CNG Facility - North of Watford City on Hwy 1806, then west on 40th St NW about 300ft.

Submitted By: Jennifer Gminski

Affiliation: Ferus LP

Address: 475 - 17th St.

Ste. 420

City: Denver

State: CO

Zip: 80202

Received By:

Contact Person: Cam Jesse

5812 Jefferson Ln

Williston, ND 58801

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Tank Leak

Description of Released Contaminant: Generator oil 15W-40

Volume Spilled: 8.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Unknown - under investigation at this time.

Risk Evaluation:

None. Trained delivery personal cleaned up spill.

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Impact to soil was minor. Spill was cleaned up.

Action Taken or Planned:

Spill contained and cleaned up.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 1/19/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, 8 gallons of 15-W40 were released onto soil surface at the Banks Field CNG facility. Further followup needed.

Date: 1/21/2016 **Status:** Inspection

Author: Cooper, Mike

Updated Volume:

Notes:

Arrived on site at 2:55 p.m. 16 degrees F, wind 0-5 mph. No contamination was visible. Did not see any contamination in the ditch near location or within the proximity. Further correspondance is necessary to check on disposal of material from spill. Spill is believed to have happened on the roadway itself.