

General Environmental Incident Summary

Incident: 4028 **Date/Time Notice:** 2/29/2016 **DEM Incident No:**

Responsible Party: Unknown

Date Incident: 2/29/2016 **Time Incident:** 2/29/2016 **Duration:**

County: Renville **Twp:** 161 **Rng:** 84 **Sec:** 13 **Qtr:**

Lat: 48.76392 **Long:** -101.50090 **Method:** Interpolation from map

Location Description: 102 Industrial Ave, Farmers Union Oil Company Mohall/Sherwood

Submitted By: Travis Halvorson

Affiliation:

Address: 102 Industrial Ave

City: Mohall

State: ND

Zip: 58761

Received By:

Contact Person:

unkown

unknown, ND

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: unknown

Description of Released Contaminant: unknown

Volume Spilled:

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Discovered while doing a spring lot inspection.

Risk Evaluation:

none

of Fatalities:

of Injuries:

Affected Medium: 04 - water and soil

Potential Environmental Impacts:

unknown

Action Taken or Planned:

Contacted Scott Brown with Strata Corp. He recommends cleaning up the mess on our property and dealing with state right away later.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 3/1/2016 **Status:** Inspection

Author: Souder, Taylor

Updated Volume:

Notes:

More follow-up needed.

Date: 3/2/2016 **Status:** Inspection

Author: Torgerson, Brad

Updated Volume:

Notes:

Visited the Cenex/Farmers Union Oil Co. (FUO) station in Mohall on March 2, 2016. Met with Phyllis Hyatt and Doug Brendsel of FUO and Scott Brown of Strata. An unknown oily substance was reportedly spilled on the SE area of the FUO property, just south of the FUO east pump island. Reportedly, when the snow melted the oily substance travelled south to a ditch along the north side of Hwy 5 and traveled east (see picture). At the time of my visit, Strata was in the process of excavating oily soil at the SE area of the FUO property. According to Mr. Brown of Strata, the oily excavated soil was going to be transported for disposal at the Clean Harbors Sawyer Industrial Waste Landfill. During my visit, Strata placed sorbent pom-poms at a culvert inlet and outlet just east of the FUO property (see pictures). According to Mr. Brown, three soil grab samples were collected from the ditch area. The grab samples were screened with a photoionization detector (PID), and the volatile organic compound (VOC) levels were <2 parts per million (PPM). At the time of the visit, oily stained vegetation was observed within the ditch. Based on the low soil PID readings, Strata recommended no further excavation but to monitor the vegetation in the future.