

# General Environmental Incident Summary

**Incident:** 4045      **Date/Time Notice:** 3/21/2016      2130      **DEM Incident No:**

**Responsible Party:** Magellan Pipeline Co., LP

**Date Incident:** 3/21/2016      **Time Incident:** 1900      **Duration:**

**County:** Cass      **Twp:** 141      **Rng:** 49      **Sec:** 33      **Qtr:**

**Lat:** 46.98014      **Long:** -96.88269      **Method:** Interpolation from map

**Location Description:** 83 Lind Lane, Harwood, North Dakota

**Submitted By:** Scott Benik

**Affiliation:** Magellan

**Address:** 2728 Patton Road

**City:** St. Paul

**State:** MN

**Zip:** 55113

## Received By:

**Contact Person:** Scott Benik  
2728 Patton Road  
St. Paul, MN 55113

**Distance Nearest Occupied Building:** 25 Feet      **Release Contained:** No

**Type of Incident:** Pipeline Leak

**Description of Released Contaminant:** Gasoline

**Volume Spilled:** 100.00 barrels      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** Yes

## Cause of Incident:

Pinhole release in a 6-inch diameter refined petroleum products pipeline. Precise location has not been identified yet. Emergency one-call notification has been made. Excavation contractor will be onsite to begin excavating and exposing the pipeline.

## Risk Evaluation:

Homeowner has been evacuated due to gasoline odor in his basement.

**# of Fatalities:**      **# of Injuries:**      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

Soil impacts.

## Action Taken or Planned:

Pipeline has been shutdown. Magellan personnel are working with local emergency responders to determine release location.

Homeowner notified Magellan of a gasoline odor in his basement and sheen within his basement's sump basket. The homeowner was evacuated by local fire dept.

NRC Report No. 1143412

**Wastes Disposal Location:** TBD.

**Agencies Involved:** Local Fire Department, Local Law Enforcement

### **Updates**

---

**Date:** 3/21/2016    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Volume:**

**Notes:**

According to the incident summary, this spill impacted the surrounding area. More follow-up is necessary.

---

**Date:** 3/22/2016    **Status:** Correspondence

**Author:** Stockdill, Scott

**Updated Volume:**

**Notes:**

Spoke with company representative.

The responsible party will begin to do soil borings tomorrow and is in the process of delineation. According to the responsible party, the released amount appears to be accurate. They are planning to remove 1000 yards of impacted soil. The local fire and police departments went door to door in the neighborhood to find out if any other homeowners have reported the smell of gasoline. There haven't been any reports, and the responsible party and the fire department are currently checking on the presence of odors in the neighboring buildings.

More follow-up is necessary to ensure proper cleanup.

---

**Date:** 3/23/2016    **Status:** Inspection

**Author:** Souder, Taylor

**Updated Volume:**

**Notes:**

Received these updates from Fargo office field staff. Excavation is being continued closer to the house. Geoprobng has begun and will continue through the rest of the week. Photoionization detector (PID) readings were taken throughout the neighborhood with results coming back clear. The pipe has been permanently fixed. Photos can be found in the report folder.