

# General Environmental Incident Summary

**Incident:** 4089      **Date/Time Notice:** 5/9/2016      0930      **DEM Incident No:**  
**Responsible Party:** Sterling Construction Management  
**Date Incident:** 5/7/2016      **Time Incident:** 1415      **Duration:** 2 minutes  
**County:** Dunn      **Twp:** 148      **Rng:** 97      **Sec:** 35      **Qtr:**  
**Lat:** 47.59975      **Long:** -103.00120      **Method:** Navigation quality GPS  
**Location Description:** ONEOK Bear Creek NGL Pipeline (currently under construction). There are no direct access roads to this location. Contact Todd Kelvington at ONEOK if site visits are necessary.  
**Submitted By:** Todd Kelvington      **Affiliation:** ONEOK  
**Address:** 100 West 5th Street  
**City:** Tulsa      **State:** OK      **Zip:** 74103

## Received By:

**Contact Person:** Derrick Ingle  
10020 HWY 200 East  
Dunn Center, ND 58626

**Distance Nearest Occupied Building:** 2 Miles      **Release Contained:** Yes

**Type of Incident:** Equipment failure

**Description of Released Contaminant:** Hydraulic Oil

**Volume Spilled:** 2.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** Unknown

## Cause of Incident:

Hydraulic line failure on excavator

## Risk Evaluation:

None. Immediate response was achieved.

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

Not likely. No resources or receptors present in the immediate vicinity. Impacted soils were immediately excavated and the pipeline ROW will experience additional excavation and restoration activities during construction.

## Action Taken or Planned:

Contractor shut equipment down and deployed spill kits. Impacted soils and spill kit supplies were bagged and taken to Sterling Construction yard.

**Wastes Disposal Location:** Total Control is under contract by Sterling Construction to dispose of contaminated project waste.

## Agencies Involved:

## **Updates**

---

**Date:** 5/9/2016    **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

### **Updated Volume:**

### **Notes:**

According to the report, 2 gallons of hydraulic oil were released on a pipeline right-of-way. More follow-up is needed.

---

**Date:** 5/11/2016    **Status:** No Further Action Requested

**Author:** Kannenberg, Derek

### **Updated Volume:**

### **Notes:**

On site: 1648

Weather: Cool. Wind and temp not noted.

Site has been remediated. Removed soil has been bagged and, in some cases, disposed of. The site is clean and neat, and appears to be well managed. Requested photos of spills in the future. No further action required.