

# General Environmental Incident Summary

**Incident:** 4095      **Date/Time Notice:** 5/17/2016      1315      **DEM Incident No:**  
**Responsible Party:** WBI Energy Transmission  
**Date Incident:** 5/16/2016      **Time Incident:** 1600      **Duration:** 1 minutes  
**County:** McKenzie      **Twp:** 150      **Rng:** 98      **Sec:** 2      **Qtr:**  
**Lat:** 47.84681      **Long:** -103.18540      **Method:** Interpolation from map  
**Location Description:** From Watford City head north on HWY#1806 approximately 3 miles. Turn right on 30 St NW and go 3/4 mile. Turn right onto pipeline R/W and go 500 feet.  
**Submitted By:** Greg Huncovsky      **Affiliation:**  
**Address:** 2010 Montana Ave.  
**City:** Glendive      **State:** MT      **Zip:** 59330

## Received By:

**Contact Person:** Greg Huncovsky  
2010 Montana Ave.  
Glendive, MT 59330

**Distance Nearest Occupied Building:** 1000 Feet      **Release Contained:** Yes

**Type of Incident:** Hydraulic Leak

**Description of Released Contaminant:** Hydraulic Fluid

**Volume Spilled:** 0.13 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** No

## Cause of Incident:

A small hydraulic leak developed on a track-hoe working on the pipeline R/W.

## Risk Evaluation:

None.

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

Contaminated soil was promptly removed and bagged for disposal. Further environmental impacts are highly unlikely.

## Action Taken or Planned:

Diapers from a spill kit were used to wipe off the machine. Contaminated soil was removed and bagged for disposal. Crews will monitor equipment to ensure leaks do not persist.

**Wastes Disposal Location:** Waste will be stored on location in a sealed drum for the duration of the project. Upon project completion this waste, and contaminated soils from any other spills will be trucked to an approved landfill.

## Agencies Involved:

## **Updates**

---

**Date:** 5/17/2016    **Status:** Reviewed - Follow-up Required

**Author:** Espe, Brady

**Updated Volume:**

**Notes:**

According to the report, the release occurred on a pipeline right-of-way. More follow-up is needed.

---

**Date:** 6/2/2016    **Status:** Inspection

**Author:** O'Gorman, Brian

**Updated Volume:**

**Notes:**

Arrived on location at 9:09. 61 degrees F, sunny, SE wind 10-15 mph. Followed directions to location described on report and walked along pipeline right-of-way using GPS coordinates for release point. Observed the area and took photos. Did not notice any petroleum-impacted soils along the area described. No further follow-up needed at this time.