

General Environmental Incident Summary

Incident: 4098 **Date/Time Notice:** 5/17/2016 1725 **DEM Incident No:**
Responsible Party: Casedhole Solutions
Date Incident: 5/15/2016 **Time Incident:** 1530 **Duration:** 12 minutes
County: Mountrail **Twp:** 154 **Rng:** 90 **Sec:** 35 **Qtr:**
Lat: 48.12444 **Long:** -102.22440 **Method:** Interpolation from map
Location Description: Intersection of 49th & 74th of Mountrail County

Submitted By: John Rogers **Affiliation:**
Address: 13568 58th Street NW
City: Williston **State:** ND **Zip:** 58801

Received By:

Contact Person: Eric Hansen
4946 HWY 85 South
Williston, ND 58801

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: Equipment Leak

Description of Released Contaminant: Dypex Wireline Lubricating Oil

Volume Spilled: 10.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

Fluid build up in catch pan was built up over job duration and rainy conditions. Build up was not properly contained before equipment was moved from well site. During transit, fluid leaked onto roadway during stop and go travel.

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Slight possibility of residual spreading to soil near impacted site.

Action Taken or Planned:

Sand and "Floor Dry"/absorbent was spread out on spilled area. The material was swept up and transported back to Williston Shop.

Wastes Disposal Location:

Agencies Involved: State Highway Patrol, Local Fire Department, Local Law Enforcement, Local Emergency Manager

Updates

Date: 5/17/2016 **Status:** Reviewed - Follow-up Required

Author: Espe, Brady

Updated Volume:

Notes:

According to the report, the release occurred on road. More follow-up is needed.

Date: 5/27/2016 **Status:** Inspection

Author: Kangas, Kathleen

Updated Volume:

Notes:

On site 05.26.16 at 3:30 p.m. 66 degrees F, cloudy, wind 9 mph west. Inspected the intersection of Hwy 3 (74th) and 49th. Report indicates material was cleaned up. Site inspection appears to show no remaining impact.

Took photos standing on the east side of Hwy 3 facing westward.

Photo 864 - Looking NW of intersection

Photo 865 - Looking SW of intersection

Photo 866- Looking west