

# General Environmental Incident Summary

**Incident:** 4166      **Date/Time Notice:** 7/14/2016      13:45      **DEM Incident No:**  
**Responsible Party:** HESS CORPORATION

**Date Incident:** 7/13/2016      **Time Incident:** 2:31      **Duration:** 1 hours  
**County:** McKenzie      **Twp:** 150      **Rng:** 95      **Sec:** 8      **Qtr:** NE

**Lat:** 47.82206      **Long:** -102.87180      **Method:** Navigation quality GPS

**Location Description:** SOUTH OF KEENE ON 23 GO EAST ON COUNTY ROAD 14, APPROX 6 MILES TO THE ROW ON THE WEST SIDE OF HWY 14. WEST APPROX 2500 FEET, GO SOUTH 2000 FEET AND THEN WEST 750 FEET.

**Submitted By:** JAKE KOLAR      **Affiliation:** WYATT

**Address:** 2292 N CARDINAL

**City:** AZLE      **State:** TX      **Zip:** 76020

## Received By:

**Contact Person:** ROB DRYSDALE  
1501 MCKINNEY ST  
HOUSTON, TX 77010

**Distance Nearest Occupied Building:** 1 Miles      **Release Contained:** Yes

**Type of Incident:** POLY LINE STRIKE

**Description of Released Contaminant:** FRESH WATER/ SALT WATER

**Volume Spilled:** 85.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Unknown

## Cause of Incident:

231 PM TRENCHING AND HIT A 2" AND 3" POLY THAT WERE ON TOP OF EACH OTHER, AT THAT TIME WE STOPPED TRENCHING AND CONTACTED HESS TO VERIFY IF IT WAS THERE LINE BECAUSE THEY HAD LINES STAKED OUT 750' EAST OF THE LOCATION, AT THAT TIME THE LOCATOR CAME OUT AND SAID HE BELIEVED IT WAS THEIR LINES. HE CONTACTED A VAC TRUCK THAT CAME OUT AND REMOVED WATER FROM TRENCH LINE. THERE WAS NO OTHER RELEASE AS LINES WERE NOT PRESSURIZED.

## Risk Evaluation:

NONE KNOWN

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

NONE KNOWN

## Action Taken or Planned:

231 PM TRENCHING AND HIT A 2" AND 3" POLY THAT WERE ON TOP OF EACH OTHER, AT THAT TIME WE STOPPED TRENCHING AND CONTACTED HESS TO VERIFY IF IT WAS THERE LINE BECAUSE THEY HAD LINES STAKED OUT 750' EAST OF THE LOCATION, AT THAT TIME THE LOCATOR CAME OUT AND SAID HE BELIEVED IT WAS THEIR LINES. HE CONTACTED A

VAC TRUCK THAT CAME OUT AND REMOVED WATER FROM TRENCH LINE. THERE WAS NO OTHER RELEASE AS LINES WERE NOT PRESSURIZED.

**Wastes Disposal Location:** HESS REMOVED ALL FLUIDS AND DISPOSED OF THEM AT A LOCATION UNKNOWN TO WYATT CONSTRUCTION.

**Agencies Involved:**

### **Updates**

---

**Date:** 7/14/2016    **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

**Updated Volume:**

**Notes:**

Release, due to a damaged saltwater/freshwater line, impacted soils along a pipeline right-of-way. More follow-up needed.

---

**Date:** 7/20/2016    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Volume:**

**Notes:**

Arrived on location 7:09, 7/20/2016

No sign of spill at the time of inspection. Recent earthwork done due to a pipeline being installed. Contact responsible party to ensure proper cleanup.

More follow-up is necessary.