

General Environmental Incident Summary

Incident: 4180 **Date/Time Notice:** 7/29/2016 **DEM Incident No:**
Responsible Party: FM excavating
Date Incident: 7/29/2016 **Time Incident:** 14:45 **Duration:** 15 minutes
County: Cass **Twp:** 138 **Rng:** 49 **Sec:** 5 **Qtr:** SE
Lat: 46.79626 **Long:** -96.89148 **Method:** Interpolation from map
Location Description: 6029 59 avenue s, Fargo ND, new development.

Submitted By: Mike Mead **Affiliation:**
Address: 4100 32 ave sw
City: Fargo **State:** ND **Zip:** 58104

Received By:

Contact Person:
9792 US-75,,
Moorhead, MN 56560

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: Contractor hit and moved electrical transformer

Description of Released Contaminant: Mineral oil

Volume Spilled: 1.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

Contractor backfilling newly poured basement hit and moved the transformer. This caused wire to burnt a small hole in transformer tank causing a small leak less than one gallon.

Risk Evaluation:

None

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

None, we cleaned up effected area.

Action Taken or Planned:

soaked up what little oil spilled, and replaced transformer. New transformer no PCB per manufacture label. as Per out policy we will take a sample and retest oil.

Wastes Disposal Location: If test is OK we will dispose of in landfill. If test show PCB we will disposed of with our hazardous disposal company.

Agencies Involved:

Updates

Date: 8/2/2016 ***Status:*** Reviewed - Assigned to NDDoH Division ***Author:*** Souder, Taylor

Updated Volume:

Notes:

This release will be handled by personnel in the Division of Waste Management at the NDDoH.