

General Environmental Incident Summary

Incident: 4182 **Date/Time Notice:** 8/1/2016 1155 **DEM Incident No:**

Responsible Party: 5th Bomb Wing

Date Incident: 7/27/2016 **Time Incident:** 1300 **Duration:**

County: Ward **Twp:** 157 **Rng:** 83 **Sec:** 13 **Qtr:** SW SE SW

Lat: 48.41530 **Long:** -101.33360 **Method:** Navigation quality GPS

Location Description: Corner of Peacekeeper Place and Bomber Boulevard on Minot AFB, 13 miles north of Minot, ND.

Submitted By: Danny Kluck

Affiliation:

Address: 5 CES/CEIEC

445 Peacekeeper Place

City: Minot AFB

State: ND

Zip: 58705

Received By:

Contact Person: Danny Kluck
201 Summit Drive
Minot AFB, ND 58705

Distance Nearest Occupied Building: 500 Feet **Release Contained:** Yes

Type of Incident: Pump Leak

Description of Released Contaminant: mogas

Volume Spilled: 300.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Yes

Cause of Incident:

A broken connection/pipe beneath the pedestal for the GUR pump began leaking fuel to an underground concrete pit on the northeast side of the ASTs at the Military Service Station.

Risk Evaluation:

None.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 01 - air

Potential Environmental Impacts:

None. Release was 100% contained - it did not reach water or soil.

Action Taken or Planned:

Fuel flow was shut off and the connection was repaired. The fuel that was contained in the concrete pit was removed. Fuel residue in the concrete pit was mopped up with absorbent pads.

Wastes Disposal Location: The recovered fuel was recycled and the absorbent pads were disposed of through the base HAZMART.

Agencies Involved: USAF

Updates

Date: 8/1/2016 ***Status:*** Reviewed - No Action Required

Author: Souder, Taylor

Updated Volume:

Notes:

According to the report, the release was contained within the underground containment system. No action needed at this time.