

General Environmental Incident Summary

Incident: 583 **Date/Time Notice:** 2/28/2003 1400 **DEM Incident No:**

Responsible Party: Martin Oil Company

Date Incident: 2/28/2003 **Time Incident:** 1300 **Duration:** 5 minutes

County: Emmons **Twp:** 132 **Rng:** 76 **Sec:** 17 **Qtr:**

Lat: 46.25434 **Long:** -100.22230 **Method:** Derived from TRS

Location Description: Martin Oil in Linton, ND. Overfill occurred at their bulk storage facility on the south edge of town.; AH - 10/26/2012 - Could be Section 8.

Submitted By: Calvin Martin

Affiliation:

Address:

City:

State:

Zip:

Received By: Gary Berreth

Contact Person: Kal Martin
214 Broadway S
Linton, ND 58552

Distance Nearest Occupied Building: 500 Feet

Type of Incident: tank overflow

Description of Released Contaminant: No. 1 and No. 2 dyed-diesel

Volume Spilled: 250.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Fuel supplier placed delivery hose into wrong AST. The tanks was overfilled and fuel spilled out onto the ground within the containment dike.

Risk Evaluation:

None

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

The diked containment area is not lined. Spilled fuel could eventually migrate down to groundwater.

Action Taken or Planned:

Fuel is contained within diked area. Product was being pumped up and into a fuel truck for transport back to fuel supplier. Remaining fuel will be soaked up with floor dry. Department personnel will visit the site next week to determine future action and determine disposal options for contaminated soil, etc.

Wastes Disposal Location: Fuel will be trucked back to Economy Oil- Oakes, ND. A disposal site for contaminated soil, etc. has not been arranged as yet.

Agencies Involved:

