

General Environmental Incident Summary

Incident: 991 **Date/Time Notice:** 4/24/2008 1428 **DEM Incident No:**
Responsible Party: American Crystal Sugar Company
Date Incident: 4/24/2008 **Time Incident:** 1200 **Duration:** 1 hours
County: Pembina **Twp:** 159 **Rng:** 51 **Sec:** 14 **Qtr:**
Lat: 48.59303 **Long:** -97.17905 **Method:** Derived from TRS
Location Description: 8152 County Highway 44 North, Drayton, ND

Submitted By: Ron Koester **Affiliation:**
Address:
City: **State:** **Zip:**

Received By: Gary Berreth
Contact Person: Ron Kester
Route 2, Box 42
PO Box 190
Drayton, ND 58225-0190

Distance Nearest Occupied Building: 2 Miles
Type of Incident: tank leak
Description of Released Contaminant: Sulfur Dioxide
Volume Spilled: 1.00 pounds **Ag Related:** No
EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:
American Crystal Sugar Co. truck hooked up to delivery tanker truck. Leak appeared to be coming from the hose connection.

Risk Evaluation:
None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 01 - air

Potential Environmental Impacts:
None

Action Taken or Planned:
The release was monitored with a hand-held SO₂ monitor. Strong winds prevented any detection of SO₂. The American Crystal Sugar Co. truck was disconnected from the delivery truck. It appeared that a secondary valve had failed. The primary valve functioned properly; the leak was stopped, and the delivery truck was released back onto the highway.

Wastes Disposal Location: NA
Agencies Involved: NDDDES

