

Oil Field Environmental Incident Summary

Incident: TMC00000008 **Date/Time of Notice:** 02/08/2013 10:30

Responsible Party:

Well Operator: HESS CORPORATION

Well Name: EN-D CVANCARA-154-93- 0409H-1

Field Name: ROBINSON LAKE

Well File #: 17562

Date Incident: 1/17/2013 **Time Incident:** 00:00

Facility ID Number:

County: MOUNTRAIL

Twp: 154

Rng: 93

Sec: 4

Qtr: LO 3

Location Description:

Submitted By: Kerry Bruns

Received By:

Contact Person:

3015 16TH ST SW STE 20
MINOT, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Miles

Distance Nearest Water Well: 1 Miles

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3.2	barrels	3.2	barrels	3.2	barrels
Brine	0	barrels	0	barrels	0	barrels
Other	0.8	barrels	0.8	barrels	0.8	barrels

Description of Other Released Contaminant:

OBM

Inspected:

Written Report Received: 10/19/2015

Clean Up Concluded: 1/17/2013

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

Action Taken or Planned:

100% of the OBM was able to be cleaned up. Spill cleaned up using the rigs vacuum system and the remainder was scooped and mixed with the fly ash, dried and properly disposed of in the dry cuttings pit on site.

Wastes Disposal Location: The dry cuttings pit on site

Agencies Involved:

Updates

Date: 2/8/2013 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release occurred on location, apparently during drilling and was contained within the diking, according to the report.