

Oil Field Environmental Incident Summary

Incident: 20121217102138 **Date/Time of Notice:** 12/17/2012 10:09

Responsible Party: Christopher Clark

Well Operator: LIBERTY RESOURCES LLC

Well Name: LASSEY-MYERS 1

Field Name: GLASS BLUFF

Well File #: 10921

Date Incident: 11/26/2012 **Time Incident:** 22:30

Facility ID Number:

County: MCKENZIE

Twp: 152 **Rng:** 103 **Sec:** 28 **Qtr:** SW SE

Location Description:

Submitted By: Christopher Clark

Received By:

Contact Person: Chris Clark
1200 17TH ST STE 2050
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 3492 Feet

Distance Nearest Water Well: 3492 Feet

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels		
Brine	4	barrels	4	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Areal Extent:

Potential Environmental Impacts:

Action Taken or Planned:

Spill was vacuumed up. Truck drivers are required to gauge tanks prior to offloading.

Wastes Disposal Location: Water was vacuumed up and placed back into tank when levels dropped.

Agencies Involved:

Updates

Date: 12/17/2012 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report.