

Oil Field Environmental Incident Summary

Incident: 20130722132811 **Date/Time of Notice:** 07/22/2013 12:10

Responsible Party: Murex Petroleum

Well Operator: MUREX PETROLEUM CORPORATION

Well Name: AXEL HOUMANN 2

Field Name: SOUTH WESTHOPE

Well File #: 2080

Date Incident: 7/20/2013 **Time Incident:** 07:00

Facility ID Number:

County: BOTTINEAU

Twp: 162

Rng: 80

Sec: 15

Qtr:

Location Description:

Submitted By: Kyle Ledbetter

Received By:

Contact Person: Johan Garcia
515 N SAM HOUSTON PKY E
Suite 485
HOUSTON, TX 77060

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Miles

Distance Nearest Water Well: 0.5 Miles

Type of Incident: Treater Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	gallons	4	gallons		
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

N/A

Potential Environmental Impacts:

None

Action Taken or Planned:

Fire extinguished by isolating leak and throwing sand on fire. Murex Foreman called state inspector Scott Dihle at 08:00 Saturday 7/20 to notify him of incident. Vac truck sucked up remaining fluid on ground. Vic clamp replaced.

Wastes Disposal Location: Back in oil tank at location.

Agencies Involved:

Updates

Date: 7/23/2013 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location, within the treater dike, according to the report.