

# Oil Field Environmental Incident Summary

**Incident:** 20140106165857      **Date/Time of Notice:** 01/06/2014 16:49

**Responsible Party:** STATOIL OIL & GAS LP

**Well Operator:** STATOIL OIL & GAS LP

**Well Name:** DOMINEK 13-24 1-H

**Field Name:** TODD

**Well File #:** 21499

**Date Incident:** 1/3/2013      **Time Incident:** 1100

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 154      **Rng:** 102      **Sec:** 13      **Qtr:**

**Location Description:** 2 barrels of oil release into flare pit and light spray along side and top of location berm.

**Submitted By:** Jake Way

**Received By:**

**Contact Person:** Wade Bragg  
6300 BRIDGE POINT PKY, BLDG 2  
SUITE 500  
AUSTIN, TX 78730

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 2 Miles

**Distance Nearest Water Well:** 2 Miles

**Type of Incident:** Other

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	2	barrels	2	barrels		
<b>Brine</b>	0	barrels	0	barrels		
<b>Other</b>	0	barrels	0	barrels		

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

Possible inhalation of hydrocarbons during cleanup response.

**Areal Extent:**

Approx 45 sq feet on top of berm

**Potential Environmental Impacts:**

Very little impact of intrusion into soil or water.

**Action Taken or Planned:**

Well was immediately shut in and environmental cleanup company called to dispose of product.

**Wastes Disposal Location:** Newalta

**Agencies Involved:**

**Updates**

---

**Date:** 1/10/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Incident date year is incorrect. Should be 2014. Release to flare pit from treater upset, and spray off location was not contained completely on location. Followup is necessary.

---

**Date:** 1/22/2014    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

1/22/2014 at 11:14, on location. No stain visible on dirt or snow of berm, no stain visible in vegetation/snow adjacent to south side of berm by flare pit. However, a shovel with noticeable staining and some impacted material in it was visible on berm in this area. Notified contact of need to remove shovel.