

# Oil Field Environmental Incident Summary

**Incident:** 20140131100851      **Date/Time of Notice:** 01/31/2014 08:54  
**Responsible Party:** Denbury Onshore  
**Well Operator:** DENBURY ONSHORE, LLC  
**Well Name:** MILLER CTB  
**Field Name:** CEDAR HILLS      **Well File #:** 0  
**Date Incident:** 1/30/2014      **Time Incident:** 09:00      **Facility ID Number:** 413695-17  
**County:** BOWMAN      **Twp:** 132      **Rng:** 106      **Sec:** 33      **Qtr:** NE SW  
**Location Description:** On location

**Submitted By:** Josh Cuppy      **Received By:**  
**Contact Person:** Josh Cuppy  
5320 LEGACY DR  
PLANO, TX 75024-3127

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 2 Miles  
**Distance Nearest Water Well:** 2 Miles

**Type of Incident:** Treater Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	5	barrels	5	barrels	5	barrels
<b>Brine</b>	40	barrels	40	barrels	40	barrels
<b>Other</b>	0	barrels	0	barrels		

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 2/17/2016      **Clean Up Concluded:** 5/4/2015

**Risk Evaluation:**  
none

**Areal Extent:**

**Potential Environmental Impacts:**

None-All contained within facility diking.

**Action Taken or Planned:**

Released fluid was recovered. Impacted area washed and recovered.

**Wastes Disposal Location:**

**Agencies Involved:** BLM

**Updates**

---

**Date:** 2/4/2014    **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a treater leak, remained on location within the diking, according to the report. NDIC retains oversight.