

Oil Field Environmental Incident Summary

Incident: 20140630121821 **Date/Time of Notice:** 06/30/2014 12:18
Responsible Party: DENBURY ONSHORE, LLC
Well Operator: DENBURY ONSHORE, LLC
Well Name: THIELEN 1-23H
Field Name: CROOKED CREEK **Well File #:** 15032
Date Incident: 6/29/2014 **Time Incident:** 08:00 **Facility ID Number:**
County: DUNN **Twp:** 143 **Rng:** 97 **Sec:** 23 **Qtr:**
Location Description: ON SITE-reported to Rick Hutchens NDIC at 0700 2014-06-30

Submitted By: Josh Cuppy **Received By:**
Contact Person: Brian Ehrmantraut
5320 LEGACY DR
PLANO, TX 75024-3127

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building: 3 Mile
Distance Nearest Water Well: 3 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	15	Barrels	15	Barrels	15	barrels
Other						

Description of Other Released Contaminant:
None

Inspected: **Written Report Received:** 2/17/2016 **Clean Up Concluded:** 9/29/2014

Risk Evaluation:
None

Areal Extent:
On site

Potential Environmental Impacts:

None

Action Taken or Planned:

The well was shut down and the the tank was emptied. A vac truck sucked up the standing fluid from within the dikes and the fluid was hauled to a SWD. The contaminated soil will be excavated and hauled to an approve landfill.

Wastes Disposal Location: SWD and landfill.

Agencies Involved: BLM

Updates

Date: 6/30/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location within the dikes. NDIC retains oversight.