

Oil Field Environmental Incident Summary

Incident: 20140717082842 **Date/Time of Notice:** 07/17/2014 08:28

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: BB-CHAPIN 151-95-0506H-2

Field Name: BLUE BUTTES

Well File #: 25057

Date Incident: 7/16/2014 **Time Incident:** 10:25

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 95

Sec: 5

Qtr:

Location Description:

Submitted By: Jason Henry

Received By:

Contact Person: Jason Henry
3015 16th Street SW, Suite 20
Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Mile

Distance Nearest Water Well: 0.5 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Barrels			10	barrels
Brine	5	Barrels				
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 11/27/2015

Clean Up Concluded: 12/31/2014

Risk Evaluation:

N/A - The released emulsion remained in the wellhead cellar.

Areal Extent:

The release was contained on the well location.

Potential Environmental Impacts:

The release occurred above ground and remained on the well location.

Action Taken or Planned:

The wellhead will be repaired, and a vacuum truck will be dispatched to recover the emulsion from the wellhead cellar.

Wastes Disposal Location: At a properly permitted disposal facility.

Agencies Involved:

Updates

Date: 7/17/2014 **Status:** Reviewed - Assigned to Other Agency **Author:** Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location within the diking according to the report. NDIC retains oversight.