

Oil Field Environmental Incident Summary

Incident: 20140811170458 **Date/Time of Notice:** 08/11/2014 17:04

Responsible Party: Enduro Operating

Well Operator: ENDURO OPERATING, LLC

Well Name: NSCU Satellite 10 CTB

Field Name: NEWBURG

Well File #:

Date Incident: 8/11/2014 **Time Incident:** 09:00 **Facility ID Number:** 401505-10

County: BOTTINEAU **Twp:** 161 **Rng:** 79 **Sec:** 23 **Qtr:** NW NW

Location Description: CTB

Submitted By: Bryan Pease

Received By:

Contact Person: Bryan Pease
777 MAIN STREET
SUITE 800
FORT WORTH, TX 76102

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Barrels	5	Barrels	5	barrels
Brine	40	Barrels	40	Barrels	40	barrels

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 2/26/2016

Clean Up Concluded: 8/14/2014

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Replaced valve on pump. Sucked up emulsion from within the Dike and put into tanks and will clean up affected facility gravel with skid steer and put into Prairie Waste Disposal container.

Wastes Disposal Location: Water to our disposal and oil into the oil tank. affected facility gravel to Prairie Waste Disposal.

Agencies Involved:

Updates

Date: 8/13/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/pipeline leak, remained on location within the diking according to the report. NDIC retains oversight.